8585 WOODWAY DR. VERANDA APTS HOUSTON, TX 77063

Inquiry Number: December 11, 2013

EDR Site Report[™]




TABLE OF CONTENTS

The EDR-Site Report[™] is a comprehensive presentation of government filings on a facility identified in a search of federal, state and local environmental databases. The report is divided into three sections:

Section	on 1: Facility Summary	3
	Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.	
Section	on 2: Facility Detail Reports	• 4
	All available detailed information from databases where sites are identified.	
Section	on 3: Databases and Update Information	e 5
	Name, source, update dates, contact phone number and description of each of the databases for this report.	

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY	FACILITY 1
AREA	8585 WOODWAY DR. VERANDA APTS HOUSTON, TX 77063 EDR ID #99637752
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	YES - p4
Facility has reported hazardous material incidents to DOT (HMIRS)	NO
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in other database records (OTHER)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported emergency releases to the soil

DATABASE: Emergency Response Notification System (ERNS)

8585 WOODWAY DR. VERANDA APTS

HOUSTON, TX 77063 EDR ID #99637752

ERNS:

Site ID: 99637752

Release source: GA

8585 WOODWAY DR. VERANDA APTS HOUSTON, TX 77063 Site location:

County: **HARRIS** EPA region: NRC report number: 06 494708 F99-3909 08/11/1999 EPA report number: Spill date: Spill time: 12:15 Medium affected: Water

TRAMMELL-CROW Discharger:

8585 WOODWAY DR., VERANDA APTS HOUSTON, TX 77063-Discharger address:

Discharger county: **HARRIS** Discharger DUNŚ: Not reported

Discharger affiliation: EPA notified: True Number of injured: 0 Number of fatalities: Number of evacuees: 0 Damage: Damage \$ amount: False 0.00 Initial report: False

Updated report: True

LESS THAN 50>NEAREST CANAL Notes:

Cause code: EΑ Dumping
Not reported
Not reported
UNKNOWN OIL
0.00 UNK Spill cause: Type of agency: Responding agency: Spilled material: Spill total qty: In water: DOT #: 0.00 UNK Not reported 53897628

CAS: Quantity (lbs): 0.00

Description:

CALLER FOUND 4/5 55 GAL DRUMS IN A HOLE ABOUT 8-10 FT WIDE CALLER FOUND 4 OR 5 55 GALS DRUMS IN A HOLE ABOUT 8-10 FEET WIDE DRUMS ARE LEAKING: DRUMS ARE BLUE IN COLOR / NO ADDITIONAL MARKING

Action:

NONE
TEMP: 98F / CLOUD COVER: MODERATE / WIND: UNK *IN A HOLE ABOUT 8-10 FT WIDE,
DRUMS ARE LEAKING, DRUMS ARE BLUE IN COLOR, NO ADDITIONAL MARKING* Comments:

SECTION 3: DATABASES AND UPDATE DATES

To maintain currency of the following federal, state and local databases, EDR contacts the appropriate government agency on a monthly or quarterly basis as required.

Elapsed ASTM days: Provides confirmation that this report meets or exceeds the 90-day updating requirement of the ASTM standard.

DATABASES FOUND IN THIS REPORT

ERNS: Emergency Response Notification System
Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180

Emergency Response Notification System. ERNS records and stores information on reported releases

of oil and hazardous substances.

Date of Last EDR Contact: 10/01/2013 Date of Next Scheduled Update: 01/13/2014 Date of Government Version: 09/30/2013 Database Release Frequency: Annually